



$T_{src, in}$ sweep @ $LS = 30 \%$ $T_{src, in}$ sweep @ $LS = 40 \%$ $T_{src, in}$ sweep @ $LS = 50 \%$ α



LS sweep @ $T_{src, in} = 20$ °C LS sweep @ $T_{src, in} = 30$ °C LS sweep @ $T_{src, in} = 40$ °C LS sweep @ $T_{src, in} = 50$ °C LS sweep @ $T_{src, in} = 60$ °C α



COMP1+MOT1

VAL1

COMP2+MOT2

VAL2

SRC_HX

IHX

SNK_HX

α reference slices ($LS = 50 \%$, $T_{src, in} = 60$ °C)