



$$\dot{C}_D + \dot{Z} - R290/R600 (T_{\text{steam}} = 110^\circ\text{C})$$

$T_{\text{src, in}}$ sweep @ $LS = 30\%$ $T_{\text{src, in}}$ sweep @ $LS = 40\%$ $T_{\text{src, in}}$ sweep @ $LS = 50\%$ $\propto$



LS sweep @ $T_{\text{src, in}} = 20^\circ\text{C}$ LS sweep @ $T_{\text{src, in}} = 30^\circ\text{C}$ LS sweep @ $T_{\text{src, in}} = 40^\circ\text{C}$ LS sweep @ $T_{\text{src, in}} = 50^\circ\text{C}$ LS sweep @ $T_{\text{src, in}} = 60^\circ\text{C}$ $\propto$



COMP1+MOT1

VAL1

COMP2+MOT2

VAL2

SRC_HX

IHX

SNK_HX

$\propto$ reference slices ($LS = 50\%$, $T_{\text{src, in}} = 60^\circ\text{C}$)