




● $LS = 30\%$
 ■ $LS = 40\%$
 ▲ $LS = 50\%$
 ■ $T_{src,in} = 20\text{ }^{\circ}\text{C}$
 ■ $T_{src,in} = 30\text{ }^{\circ}\text{C}$
 ■ $T_{src,in} = 40\text{ }^{\circ}\text{C}$
 ■ $T_{src,in} = 50\text{ }^{\circ}\text{C}$
 ■ $T_{src,in} = 60\text{ }^{\circ}\text{C}$