# ServiceCipher Invoice Report

#### DATE

• June 11, 2025

## SHOP\_NAME

• Performance Tire & Auto, 1735 N Kansas Ave., Topeka, KS 66608

## REASON\_FOR\_VISIT

- Alignment issues
- Potential steering wheel misalignment
- Unusual vehicle pulling behavior

#### REPAIR\_SUMMARY

The following repair and inspection services were completed on your 2018 GMC Yukon XL to address the

## **MAJOR**

Replaced both front control arms

#### **MODERATE**

- Replaced both front ball joints
- Conducted a comprehensive wheel alignment

#### **MINOR**

Completed a courtesy inspection of the vehicle's tire and wheel conditions

## COST\_BREAKDOWN

• Control Arms (2): \$306.30

• Ball Joints (2): \$260.26

Alignment: \$119.21

Mechanic Labor: \$942.14

• Enviro & Technology Fee: \$3.88

Job Supplies: \$86.43

Subtotal: \$1718.22

• Sales Tax: \$160.65

• Total Amount Due: \$1878.87

## **EDUCATION\_SNIPPET**

Regular maintenance of your vehicle's suspension components, such as control arms and ball joints, is es

## OTHER\_NOTES

• All service work is covered by a nationwide 24-month/24,000-mile warranty. For any inquiries or issues, p

## **RECOMMENDATIONS**

- Monitor vehicle handling and steering for any irregularities.
- Consider scheduling regular check-ups to maintain alignment and prolong the lifespan of suspension cor
- Review warranty information and be aware of the coverage terms for ongoing support.