# ServiceCipher Invoice Report

#### DATE

• June 11, 2025

### SHOP\_NAME

- Performance Tire & Auto
- Address: 1735 N Kansas Ave., Topeka, KS 66608
- Contact: mike@performancetiregroup.com, 785-354-1410

## REASON\_FOR\_VISIT

Routine maintenance and alignment check due to steering wheel issues.

## REPAIR\_SUMMARY

#### **MAJOR**

- Replaced both control arms (Part No. 810-610111B) to ensure stability and handling performance.
- Replaced both ball joints (Part No. K500408) to secure suspension integrity and avoid future misalignment

#### **MODERATE**

• Conducted a comprehensive vehicle alignment to correct the steering wheel which was previously crooked

## **MINOR**

Completed a thorough tire and wheel inspection to ensure no further issues and confirm the effectivenes.

#### COST\_BREAKDOWN

Control Arms: \$306.30 (x2) totaling \$612.60
Ball Joints: \$260.26 (x2) totaling \$520.52

Alignment Service: \$119.21Mechanic Labor: \$942.14

• Environmental & Technology Fee: \$3.88

Job Supplies: \$86.43Subtotal: \$1,718.22Sales Tax: \$160.65

• Total Amount Due: \$1,878.87

#### **EDUCATION\_SNIPPET**

• Regular alignment checks are essential, especially after reports of steering wheel misalignment, as this h

## OTHER\_NOTES

• The service provided is covered by a nationwide warranty for 24 months or 24,000 miles. For warranty in

## **RECOMMENDATIONS**

- Given the recent replacement and alignment, monitor for any further irregular steering or vibrations.
- Schedule your next routine maintenance check to prevent any future issues and ensure vehicle safety.
- Continue regular tire inspections to detect any early signs of misalignment or suspension issues.