ServiceCipher Invoice Report

DATE

- June 11, 2025

SHOP_NAME

- Performance Tire & Auto
- 1735 N Kansas Ave., Topeka, KS 66608

REASON_FOR_VISIT

- The vehicle was brought in for a scheduled alignment service.
- Customer reported a crooked steering wheel.

REPAIR_SUMMARY

- Conducted a comprehensive courtesy inspection.
- Replaced both control arms for improved suspension function.
- Replaced both ball joints to ensure proper steering and suspension alignment.
- Performed a wheel alignment to correct the crooked steering wheel.

MAJOR

- Replacement of control arms.
- Replacement of ball joints.

MODERATE

- Complete wheel alignment.

MINOR

- Courtesy inspection of the vehicle.
- Tire and wheel inspection as part of alignment service.

COST_BREAKDOWN

- Control Arm (2): \$306.30

- Ball Joint (2): \$260.26

- Alignment: \$119.21

- Mechanic Labor: \$942.14

- Environmental & Technology Fee: \$3.88

- Job Supplies: \$86.43

- Sales Tax: \$160.65

- Total Amount Due: \$1878.87

EDUCATION_SNIPPET

The control arm and ball joints are critical components of your vehicle's suspension system. The control ar

OTHER_NOTES

- The work performed is covered by a nationwide 24-month/24,000-mile warranty. Should you need assista

RECOMMENDATIONS

- Monitor the vehicle's steering and suspension feel over the next few weeks.
- Schedule regular maintenance checks to ensure ongoing vehicle safety and performance.
- If any unusual noises or handling issues persist, please contact us for a follow-up inspection.