

Screen Flicker Troubleshooting Guide

Symptoms

Affected users may experience:

- intermittent display flickering
- brightness instability
- temporary black-screen flashes
- GPU driver timeout warnings

Root Causes

Common causes include:

- outdated GPU drivers
- adaptive refresh conflicts
- overheating
- damaged display connectors
- third-party overlay software

Enterprise devices running firmware version 5.3.1 experienced elevated instability after the April update rollout.

Troubleshooting Workflow

Step 1: Restart the display service.

Step 2: Disable adaptive brightness.

Step 3: Update graphics drivers.

Step 4: Run hardware diagnostics.

Step 5: Inspect thermal readings.

If the issue persists after diagnostics, escalate to hardware support.

Known Escalation Scenario

Devices showing repeated flickering during BIOS startup are considered potential hardware failures and require immediate RMA escalation.