发件人: kathryn@biosecu.re

主题: Re: iGEM safety and security form - clarification needed

日期: 2019年8月9日 下午7:51

收件人: Johnson Zhang 897431035@qq.com

Hi there,

Thank you very much for getting back to me with such a full consideration of the reviewer feedback. I have passed the new information on to the SSC and you will hear from them soon.

Meanwhile, good luck with everything and thanks again. Your team is a fantastic example of responding quickly and comprehensively - well done!

Best wishes,

Kathryn Millett

On Thu, Aug 8, 2019 at 6:59 PM Johnson Zhang < 897431035@qq.com> wrote:

Dear reviewer

We are very grateful to get your recommendation and instruction. After we confirmed the problem we have immediately corrected the pictures on the pages https://2019.igem.org/File:T--SEU-Nanjing-China--lab1.jpeg and https://2019.igem.org/File:T--SEU-Nanjing-China--lab1.jpeg and https://2019.igem.org/File:T--SEU-Nanjing-China--lab1.jpeg and <a href="https://2019.igem.org/File:T--SEU-Nanjing-China--lab1.jpeg and <a href="https://2019.igem.org/File:T--SEU-Nanjing

are the laboratory we are working in right now, The old version of those pictures are the student laboratory where we accepted our training. As it is used for teaching, the instrument of it is kind of old. After we started experiments of our project officially, we have moved to the new laboratory (our instructor

professor Lu is in charge of this laboratory). In which picture 2 is the picture of laminar flow hood, which exactly is a ultra clean cabinet equipped with a laminar flow hood.

If there is any other issue, please point it out for us and we will work on them as soon as possible.

Thank you for you and your colleagues' guidance on our laboratory normalization!

Yours faithfully,

Zhang Ruijing

School of Biological Science & Medical Engineering, Southeast University

9/8/2019

在 2019年8月7日, 下午10:02, <u>kathryn@biosecu.re</u> 写道:

Dear Team SEU_Nanjing_China,

We have received back the review of your <u>Safety and Security Form</u>. The reviewer has identified an issue with your form that requires action:

- 1. In the lab picture, there are many improper chairs (torn covers) that may cause of contamination and pathogen accumulation in the lab. Please change the chairs or adequately repair the chair cover before use.
- 2. You have indicated the use of a laminar flow hood, however, this is not shown in your photos. Please upload a photo showing this equipment.

Please respond to these comments as soon as possible and confirm this with me by return email.

Thank you and good luck on your project!

Yours sincerely,

Kathryn Millett

Ex-officio member, iGEM Safety and Security Committee