Sprint 44 Release Note--20201113

Release Purpose:

This System release is intended System Validation

Target Audience:

• System Validation Team

Release Versions:

Device Name	Firmware Version	HardwareVersion	Date	Remark
IP GW	IPT.B.01.44.02	MP1	20201113	

New User Stories

- WISERASIA-2034 IPGW installation mode switching related definition
- LK-86 implement the Zigbee Scene feature for wiser&elko GW

Issues Fixed:

- WISERASIA-2201 2 G Curtain: Not able to commission 2G curtain on Field Trial Account.
- Fixed LK FLS configuration bug
- Fixed a bug of avatar on freelocate group/moment switch
- Fixed a bug the energy from smart socket/plug (unsigned 8-byte integer) might be out for DP range (signed 4-byte integer)

Changes:

- Supported NH shutter and puck shutter DTT_SCT_SCENE dp set
- Field_test/staging/develoment gateway should use installer pid of release environment

Known Issues:

- WISERASIA-1964 light is turned on sometimes when adding light to LK FLS group
- WISERASIA-2216 FLS adding a new member to an existent group/scene

Note:

- WISERASIA-2034 hasn't been tested, because APP is not ready
- Tuya user sdk 4.1.3 1.0.17
- Tuya installer sdk 4.1.3 1.0.11
- This firmware is not signed, please use failsafe for upgrade