

STORE INCIDENT REPORT

Severity: HIGH -- refrigeration failure with \$3,200 product loss

Location: Store #4421 -- Maple Grove, MN
Date/Time: August 14, 2026, 11:30 PM
Incident Type: Refrigeration Failure -- Frozen Cases
Reported By: Night Crew Lead -- Alex Kim
Persons Involved: Night stocking crew (6 associates). No injuries.

Incident Description

Frozen food cases in aisle 8 (doors 20-24) found at 28F during overnight stocking at 11:30 PM. Product partially thawed. Compressor rack #2 alarming -- high discharge pressure fault. Estimated 200+ units of frozen product affected across ice cream, frozen vegetables, and frozen meals.

Immediate Actions Taken

1) All affected product pulled and staged in walk-in freezer. 2) Emergency maintenance call placed at 11:45 PM. 3) Cases powered down to prevent compressor damage. 4) Product temp log started every 30 min. 5) Store manager notified at 11:50 PM.

Root Cause

Condenser fan motor failure on compressor rack #2 caused high head pressure and thermal overload. Fan motor bearings seized. Same rack services frozen cases 20-24 and backup unit was offline for scheduled maintenance.

Corrective Actions

1) Emergency fan motor replacement completed at 3:15 AM 8/15. 2) Cases restored to -5F by 6:00 AM. 3) \$3,200 in frozen product discarded. 4) Backup unit maintenance expedited. 5) Facilities to review PM schedule -- two refrigeration failures in 30 days at store #4421.