

STORE INCIDENT REPORT

Severity: LOW -- no product loss, no injuries, power restored within SLA

Location: Store #3287 -- Bloomington, MN
Date/Time: August 1, 2026, 6:15 AM
Incident Type: Equipment Failure -- Power Outage
Reported By: Kevin Park, Opening Manager
Persons Involved: Store opening crew (4 associates). No injuries.

Incident Description

Main electrical panel tripped at approximately 5:50 AM, cutting power to refrigerated cases in grocery aisles 3-7 (dairy, frozen, beverages). Backup generator activated for walk-in coolers and freezers but does not cover floor cases. Power restored by Xcel Energy at 7:45 AM. Total outage: ~2 hours.

Immediate Actions Taken

1) Verified backup generator running for walk-ins -- all walk-in temps held. 2) Spot-checked frozen case temps at 6:15 AM: -2F to 8F (acceptable). 3) Dairy reach-in temps: 38F to 44F -- borderline. 4) Placed do-not-stock holds on dairy cases until temps recovered. 5) Called Xcel Energy at 6:00 AM. 6) Temps verified recovered by 9:00 AM.

Root Cause

Xcel Energy transformer failure on distribution line. Not within store control. However, backup generator scope does not include floor-level refrigerated cases -- known gap in emergency power plan.

Corrective Actions

1) Filed claim with Xcel Energy. 2) Submitted capital request for expanded generator capacity (\$18,000 estimate). 3) Updated store emergency SOP to include temp monitoring checklist for power events.