

MAINTENANCE WORK ORDER

WO-78501 | Priority: HIGH | Status: CLOSED -- follow-up scheduled September

Location: Store #5102 -- Eden Prairie, MN
Date Opened: July 18, 2026
Date Closed: July 21, 2026
Category: HVAC
Equipment: Rooftop Unit #3 (Carrier 48TM, Serial: CAR2021-99103) -- serves bakery/deli
Reported By: Tom Nguyen, Store Manager
Assigned To: Comfort Systems USA -- Tech: Maria Santos

Problem Description

Bakery area ambient temperature reached 82F at 1 PM. RTU #3 running but not cooling. Product quality concern for cake decorating and chocolate displays.

Resolution

Found refrigerant charge low -- 4 lbs R-410A below spec. Located and repaired pinhole leak in condenser coil joint. Recharged system. Verified bakery ambient at 72F after 3 hours. Recommended condenser coil replacement at next scheduled maintenance window (September).

Cost

\$2,180.00 (labor: \$960, parts: \$120, refrigerant: \$340, leak detection: \$760)