NORTHWIND

Northwind Analytics, Inc.
Plant 3, Bay C
Date: 2026-09-15

Tallowmere Mutual Insurance Co.
Property Claims Department
400 Harbor Plaza
Portland, OR 97201

RE: Claim CLM-2026-0912 - Policy PL-2026-44718 - Date of loss 2026-09-12

Dear Claims Department,

Northwind Analytics, Inc. submits the enclosed claim under policy PL-2026-44718 for water damage at Plant 3 on 2026-09-12. A burst pipe released water into the second-floor equipment bay, damaging the ceiling, drywall, flooring and electrical systems below.

The enclosed packet includes the completed claim form, photographs of the damage with a sketch marking the leak location, our repair estimate of $36,545.00 (8 line items), and moisture readings taken on 2026-09-13. We request that an adjuster inspect the site at the earliest opportunity.

Please direct any questions to the undersigned.

Sincerely,

Dana Whitfield, Controller

Enclosures: claim form (1), photographs and leak sketch (1), repair estimate (1), moisture readings (1), adjuster summary (1)

PROPERTY DAMAGE CLAIM FORM

Tallowmere Mutual Insurance Co. - Form PD-1

Claimant name: Northwind Analytics Inc.

Policy number: PL-2026-44718

Date of loss: 2026-09-12

Cause of loss: burst pipe

Estimated loss amount: $36,545.00

Type of loss: ☐ Fire ☒ Water ☐ Wind ☐ Theft

Photos attached: ☒ Yes ☐ No

Report filed: ☐ Yes ☒ No

Claimant signature: _____

Call before site visit - ask for Bay C access

Damage Photographs and Leak Location




Photo 1. Water-stained ceiling tiles above the Server Room, taken 2026-09-13 08:42.



Photo 2. Warped floor boards below the leak, taken 2026-09-13 08:47.


Leak location sketch




Sketch (not to scale): the leak originated in the Server Room, marked in red.

Repair Estimate

Item	Category	Qty	Unit	Unit Price	Amount
Water extraction and drying	Mitigation	1	lot	$4,250.00	$4,250.00
Ceiling tile and grid replacement	Structure	340	sq ft	$14.50	$4,930.00
Drywall repair	Structure	220	sq ft	$9.25	$2,035.00
Flooring replacement	Flooring	480	sq ft	$18.00	$8,640.00
Pipe and flange repair	Plumbing	1	lot	$6,300.00	$6,300.00
Electrical inspection and rewire	Electrical	1	lot	$3,150.00	$3,150.00
Equipment relocation and storage	Contents	1	lot	$5,800.00	$5,800.00
Interior repainting	Finishes	600	sq ft	$2.40	$1,440.00
				Total	**$36,545.00**






Basis of estimate. Quantities are from the site measurements taken on 2026-09-13; unit prices are current contractor rates.


Coverage. contents and finishes are excluded under the policy, leaving $29,305.00 of $36,545.00 covered.

Deductible. A deductible of $2,500.00 applies to the covered amount.


Moisture Readings - Server Room floor grid, 2026-09-13
A 10.1 10.4 12.9 15.3 14.5 14.9 12.2 11.5
B 11.1 12.7 16.4 22.7 27.6 24.0 16.7 11.3
C 11.4 11.7 17.2 31.2 38.5 30.7 19.1 12.3
D 11.2 11.2 14.8 22.9 28.4 24.1 14.8 12.5
E 10.9 10.5 12.0 15.2 16.2 13.4 12.5 12.1
F 10.5 10.1 11.6 12.5 11.7 10.2 11.9 11.1
Grid row
1 2 3 4 5 6 7 8
Grid column
Moisture content (%)
40 35 30 25 20 15 10

Adjuster Summary

Claim CLM-2026-0912 - Policy PL-2026-44718 - Northwind Analytics, Inc.



Findings

Cause. A burst pipe at Plant 3 on 2026-09-12 released water through the second-floor slab.

Inspection. The site was inspected on 2026-09-19. Moisture mapping confirms a localized plume centred on the Server Room.

Scope. 8 estimate line items totalling $36,545.00.

Determination

Covered loss. $29,305.00.

Excluded. Contents and finishes ($7,240.00) are excluded under the policy.

Deductible. $2,500.00.

Payable. $26,805.00.

Status. Approved on 2026-09-26.

APPROVED
2026-09-26

Priya Natarajan, Senior Adjuster