

NOTES:

- 1. THE CONTRACTOR SHALL VERIFY ALL CONTROLLING FIELD DIMENSIONS BEFORE ORDERING OR FABRICATING ANY MATERIAL.
- 2. REMOVE EXISTING 2" \pm ASPHALT CONCRETE OVERLAY TO EXPOSE EXISTING CONCRETE BRIDGE DECK AND ABUTMENT BACKWALL.
- 3. THE CONTRACTOR SHALL PERFORM VISUAL AND CHAIN DRAGGING INSPECTION TO IDENTIFY AND CONFIRM LOCATIONS AND AREAS OF DEFICIENCIES.
- 4. EXISTING REINFORCEMENT MAY BE ENCOUNTERED DURING BRIDGE DECK CONCRETE REMOVAL. EXISTING REINFORCEMENT SHALL BE PROTECTED DURING UNSOUND CONCRETE REMOVAL AND PATCHING OPERATIONS.
- 5. SAW CUTTING DEPTH SHALL NOT EXCEED 1—INCH OR THE THICKNESS OF THE CONCRETE COVER OVER THE TOP LAYER OF STEEL REINFORCING BARS, WHICHEVER IS LESS.
- 6. REMOVE UNSOUND CONCRETE AND UNSOUND PATCHES TO EXPOSE SOUND CONCRETE SUBSTRATE. REPLACE WITH A FAST—SETTING, PORTLAND CEMENT OR MAGNESIUM—PHOSPHATE BASED TRAFFIC GRADE REPAIR MORTAR.
- 7. AFTER PATCHING, CLEAN AND PREPARE DECK FOR TREATMENT WITH METHACRYLATE.

LEGEND:

INDICATES LIMITS OF CLEAN AND TREAT BRIDGE DECK WITH METHACRYLATE.


INDICATES LOCATION OF REMOVE EXISTING JOINT SEAL AND PLACE NEW JOINT SEAL.

INDICATES LIMITS OF REMOVE ASPHALT CONCRETE OVERLAY.

	·			
NO.	DATE	DESCRIPTION	BY	APP.
TABLE OF REVISIONS				
THIS	DRAWING \	WAS LAST MODIFIED: 11/05/21 10:55, BY:	dleung	



REFERENCE INFORMATION & FILE NO. OF SURVEYS



		Date:	DESIGNED:	DATE:
a	Section Mgr: RAYMOND LUI	11/05/2021	JS	11/2021
	Deputy Bureau Mgr: FERNANDO CISNEROS		DRAWN:	DATE:
-	Feed L. am	12/09/2021	DL	11/2021
	Acting Bureau Mgr: IQBAL DHAPA	12/10/2021	CHECKED:	DATE:
	Truque	12/10/2021	RL	11/2021

TE:	OFFCCIO
/2021	PROFESSIONAL C. SPRINK THE
TE:	
/2021	No. S 4716 🕏
TE:	SAPUCTURANT
/2021	OF CALIFORN
	11/05/202

SSIONA	SCALE:
SPR/WEIGH	AS SHOWN
4716 🕏	SHEET OF SHEETS
TURALIFORNIA	177 OF 210

CALE:	MISSION STREET & GENEVA AVENUE				
AS SHOWN	IMPROVEMENTS PROJECT				
HEET OF SHEETS					

DECK REPAIR PLAN
BR NO. 34-0012Y

120,743

REV. NO.
0

RAWING NO.

BR-1.2