




NOTES:

- 1. THE CONTRACTOR SHALL VERIFY ALL CONTROLLING FIELD DIMENSIONS BEFORE ORDERING OR FABRICATING ANY MATERIAL.
- 2. THE CONTRACTOR SHALL PERFORM VISUAL AND CHAIN DRAGGING INSPECTION TO IDENTIFY AND CONFIRM LOCATIONS AND AREAS OF DEFICIENCIES.
- 3. EXISTING REINFORCEMENT MAY BE ENCOUNTERED DURING BRIDGE DECK CONCRETE REMOVAL. EXISTING REINFORCEMENT SHALL BE PROTECTED DURING UNSOUND CONCRETE REMOVAL AND PATCHING OPERATIONS.
- 4. SAW CUTTING DEPTH SHALL NOT EXCEED 1—INCH OR THE THICKNESS OF THE CONCRETE COVER OVER THE TOP LAYER OF STEEL REINFORCING BARS, WHICHEVER IS LESS.
- 5. REMOVE UNSOUND CONCRETE AND UNSOUND PATCHES TO EXPOSE SOUND CONCRETE SUBSTRATE. REPLACE WITH A FAST-SETTING, PORTLAND CEMENT OR MAGNESIUM-PHOSPHATE BASED TRAFFIC GRADE REPAIR MORTAR.
- 6. WHERE (E) REINFORCEMENT SECTION LOSS IS MORE THAN 25 PERCENT, OR 20 PERCENT IN TWO OR MORE ADJACENT BARS, CUT BARS AND LAP SPLICE WITH REINFORCEMENT OF THE SAME SIZE. MECHANICAL COUPLERS MAY BE USED WHERE ADEQUATE COVER CAN BE ACHIEVED.
- 7. AFTER PATCHING, CLEAN AND PREPARE DECK FOR TREATMENT WITH METHACRYLATE.

LEGEND:

INDICATES LIMITS OF RAPID SETTING CONCRETE PATCH.



BAR SIZE	MIN LAP SPLICE LENGTH
#4	1'-8"
# 5	2'-0"
#6	2'-6"



NO.	DATE	DESCRIPTION	BY	APP.
TUIC	DDAWING	TABLE OF REVISIONS	م ا	
THIS	DRAWING	WAS LAST MODIFIED: 11/05/21 10:56, BY:	aleung	



REFERENCE INFORMATION & FILE NO. OF SURVEYS



BUREAU OF ENGINEERING
CITY & COUNTY OF SAN FRANCISCO
SAN FRANCISCO PUBLIC WORKS
49 SOUTH VAN NESS AVENUE, SUITE 800
SAN FRANCISCO, CA 94103

			Date:	DESIGNED:	DATI
ì	Section Mgr:	RAYMOND LUI	11/05/2021	JS	11/2
	Deputy Bureau Mgr:	FERNANDO CISNEROS		DRAWN:	DATI
		Feel I. aim	12/09/2021	DL	11/2
	Acting Bureau Mgr:	IQBAL DHAPA	12/10/2021	CHECKED:	DATI
		Trup	12/10/2021	RL	11/2

TE:	ODEFSCIA
/2021	PROFESSIONAL C. SPRINK SIGNAL CO. SPRINK SIGNAL
TE:	
/2021	No. S 4716 \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\
TE:	ST PUCTURALITY
/2021	OF CALIFOR
	11/05/202

SCALE: AS SHOWN	MISSION STREET & GENEVA AVENUE IMPROVEMENTS PROJECT
SHEET OF SHEETS	
179 OF 210	CONCRETE REPAIR DETAILS

CONTRACT NO.

1171I

DRAWING NO.

BR-3.0

FILE NO.

120,745

REV. NO.