

Rev 1.0



* Marge R, with Rz.

* Add reference coltage with adequate amplification.

* Voltagedinder should use a reference voltage.



For had (AD