


(


SOLDAPULLT

Desoldering Tools



Tool	Replacement Tip	O-Ring
AS196	LS197 Low Static	ODS31
DS017LS	LS197 Low Static	ODS31
DS017	SRT12 Standard	ODS31
PT109	SRT12 Standard	OSB32
PT209	MRT16 Micro Tip	OSB32
PT309	LRT14 Long Tip	OSB32
PT409	LS197 Low Static	OSB32
PT509	LS315 Micro Tip	OSB32

Basic Operations



To Load
Push loading knob
down until it clicks.

Tip Replacement
Push loading knob all
the way down
pops out.