ASCENT COOPER FRAC

Soon we will begin Frac operations on the Cooper Pad.

Staging Location: Miller Farms Pad.

- **CB Channel: 27**
- **Do NOT use GPS directions to access the Miller Farms Staging Area.**
- **Utilizing unapproved routes may be suspended from all ARU operations until the completion of the frac op.**
- **Follow Ascent posted speed limits in the area.**
- **There are several Amish Families that live in the area. They are known to use unlit carriages for transportation, there are a few families that have children that travel via scooter / bicycle.**
- **The roads leading into the Staging Area as well as the Frac are narrow with quite a few blind corners and hills that block view of oncoming traffic. You will need to use your CB effectively to communicate**

Google Maps

40.2131005, -81.3915164 to Ascent Miller Farms, 19614 Sugartree Rd, Freeport, OH 43973

Drive 4.1 miles, 10 min



Imagery ©2026 Airbus, CNES / Airbus, Maxar Technologies, USDA/FPAC/GEO, Map data ©2026 1000 ft

40.2131005, -81.3915164

1. Head toward Martha Rd

259 ft

2. Turn right onto Martha Rd

0.1 mi

3. Turn left onto Titus Rd

1.3 mi

4. Turn left to stay on Titus Rd

1.0 mi

5. Sharp right onto Sligo Rd

1.2 mi

6. Turn left onto Sugartree Rd

0.5 mi

7. Turn left

⚠ Restricted usage road

ⓘ Destination will be on the right

226 ft

Ascent Miller Farms

19614 Sugartree Rd, Freeport, OH 43973

Google Maps

Ascent Miller Farms, 19614 Sugartree Rd, Freeport, OH 43973 to 73570 Tanglewood Ln, Kimbolton, OH 43749

Drive 4.8 miles, 12 min



Imagery ©2026 Airbus, CNES / Airbus, Maxar Technologies, USDA/FPAC/GEO, Map data ©2026 Google 1000 ft

Ascent Miller Farms
19614 Sugartree Rd, Freeport, OH 43973

1. Head toward Sugartree Rd
   ⚠ **Restricted usage road**

226 ft

2. Turn right onto Sugartree Rd

0.5 mi

3. Turn left onto Sligo Rd

2.7 mi

4. Turn left onto Turkey Run Rd

1.2 mi

5. Turn left onto Tanglewood Ln
   Destination will be on the right

0.4 mi

73570 Tanglewood Ln
Kimbolton, OH 43749