





1 3	PLANS PREPARED BY: E.L. ROBINSON ENGINEERING 1801 Watermark Drive, Suite 310 • Columbus, Ohio 43215 www.elrobinsonengineering.com	PLANS PREPARED FOR: CRAVAT COAL HAUL ROUTE MAP DRIVING DIRECTIONS WHEELING & SHORT CREEK TWP.S., BELMONT & HARRISON CO., OH	ASCENT RESOURCES	REV. NO.	SHEET NO.	DATE	DESCRIPTION

Z:\13065\admin\Haul Route Maps\Cravat Coal\13065 driving directions full map 2.dgn 4/20/2016 12:40:02 PM lhedges



PLANS PREPARED BY:		PLANS PREPARED FOR:	
E.L. ROBINSON ENGINEERING 1801 Watermark Drive, Suite 310 • Columbus, Ohio 43215 www.elrobinsonengineering.com		ASCENT RESOURCES	
DRIVING DIRECTIONS		CRAVAT COAL HAUL ROUTE MAP	
WHEELING & SHORT CREEK TWP., BELMONT & HARRISON CO., OH		REV. NO. DATE DESCRIPTION	
2			
3			

It is advisable to keep the attached RUMA either in all vehicles or accessible by mobile device. All oversized/overloaded vehicles will need a permit through the ODOT website. Any route applied for with ODOT that can't be navigated will kick back with an alternate route. Please contact ARU's Field Superintendent, Jeff Beck, at 614-896-0599 or jeff.beck@ascentresources.com prior to using the route. Even though ODOT approves, it still could include unauthorized roads/bridges.

[illegible]