




MADISON & LONDONDERRY TOWNSHIP, GUERNSEY CO., OH

PLANS PREPARED BY:

E.L. ROBINSON
ENGINEERING

 3001 Watermark Drive, Suite 310 • Columbus, Ohio 43215
www.elrobinsonengineering.com

[illegible]



PLANS PREPARED BY:



**HENRY
HAUL ROUTE MAP
DRIVING DIRECTIONS**

MADISON & LONDONDERRY TOWNSHIPS, GUERNSEY CO., OH

PLANS PREPARED FOR:



REV.	SHEET NO.	DATE	DESCRIPTION

Z:\13065\admin\Haul Route Maps\Henry\13065-HenryDriving Dir.dgn 5/31/2016 10:36:54 PM mcallahan

HENRY Approved RUMA Route

- From US 70:
- 1. Head northwest on SR 513 for 6 miles.
 - 2. Turn right onto US 22.
 - 3. Continue northeast on US 22 for .3 miles.
 - 4. Turn right onto McCoy Rd
 - 5. Continue east for 3.1 miles.
 - 6. Turn left onto Tyson Mill Rd.
 - 7. Continue north for 1.6 miles.
 - 8. Turn left into access road.

- From Freeport, OH:
- 1. Head south on SR 800 for 2.8 miles.
 - 2. Turn right onto US 22.
 - 3. Continue southwest for 7.9 miles.
 - 4. Turn left onto McCoy Rd.
 - 5. Continue east for 3.1 miles.
 - 6. Turn left onto Tyson Mill Rd.
 - 7. Continue north for 1.6 miles.
 - 8. Turn left into access road.

It is advisable to keep the attached RUMA either in all vehicles or accessible by mobile device. All oversized/overloaded vehicles will need a permit through the ODOT website. Any route applied for with ODOT that can't be navigated will kick back with an alternate route. Please contact ARU's Field Superintendent, Jeff Beck, at 614-896-0599 or jeff.beck@ascentresources.com prior to using the route. Even though ODOT approves, it still could include unauthorized roads/bridges.

PLANS PREPARED BY:



E.L. ROBINSON

ENGINEERING

1801 Watermark Drive, Suite 310 • Columbus, Ohio 43215

www.elrobinsoneengineering.com

PLANS PREPARED FOR:

HENRY

HAUL ROUTE MAP

DRIVING DIRECTIONS

MADISON & LONDONDERRY TOWNSHIPS, GUERNSEY CO., OH

PLANS PREPARED FOR:



REV.	SHEET NO.	DATE	DESCRIPTION

3

3