


Z:\13065\admin\Haul Route Maps\J Bar J West\13065 J BAR J WEST driving directions full map.dgn 5/13/2016 10:15:58 AM gantonios



PLANS PREPARED FOR:



J BAR J WEST
HAUL ROUTE MAP

DRIVING DIRECTIONS

OXFORD TWP., GUERNSEY CO., OH

PLANS PREPARED BY:





It is advisable to keep the attached RUMA either in all vehicles or accessible by mobile device. All oversized/overloaded vehicles will need a permit through the ODOT website. Any route applied for with ODOT that can't be navigated will kick back with an alternate route. Please contact ARU's Field Superintendent, Jeff Beck, at 614-896-0599 or jeff.ascentresources.com prior to using the route. Even though ODOT approves, it still could include unauthorized roads/bridges.