






E.L. ROBINSON
ENGINEERING
801 Watermark Drive, Suite 310 • Columbus, Ohio 43215
www.elrobinsonengineering.com

BSA
PRODUCTION TRAFFIC
HAUL ROUTE DIRECTIONS

BSA

NOTTINGHAM TWP., HARRISON CO., OH

PLANS PREPARED FOR:

[illegible]

Z:\13065\admin\Haul Route Maps\BSA\Turn by Turn Directions.dgn 4/21/2016 9:37:39 AM lhedges

BSA Approved RUMA Route*

Wheeling, WV

Head west on I-70 for 23 miles
Take exit 202 for OH-800
Turn right on OH-800 and continue 11.5 miles
Turn right onto US-22 E and drive for 0.6 miles
Turn left onto OH-800 N for 3.3 miles
Turn right onto E Main St. for 0.2 miles
Continue onto OH-800 N for 1.4 miles
Slight right onto OH-799 E for 3.2 miles
Turn left to stay on OH-799 E
Turn right onto Redeye Rd. for 0.3 miles
Turn left to continue on Redeye Rd for 2.2 miles
Turn right on Minksville Rd. for 1.9 miles
Turn right onto Bushy Fork Rd for 1.0 mile
Turn right onto Springtown Rd for 0.3 miles
Access Rd on right

Cambridge, OH

Take US-22 E for 22.2 miles
Turn left on OH-800 N for 3.3 miles
Turn right onto E Main St. for 0.2 miles
Continue onto OH-800 N for 1.4 miles
Slight right onto OH-799 E for 3.2 miles
Turn left to stay on OH-799 E
Turn right onto Redeye Rd. for 0.3 miles
Turn left to continue on Redeye Rd for 2.2 miles
Turn right on Minksville Rd. for 1.9 miles
Turn right onto Bushy Fork Rd for 1.0 mile
Turn right onto Springtown Rd for 0.3 miles
Access Rd on right

Dover, OH

Take US-250 E and continue for 9.5 miles
Take exit for US-250/OH-800 S toward Cadiz
Continue onto US-250 for 1.3 miles
Turn right on OH-800 S for 0.6 miles
Turn left onto Center St. for 0.1 miles
Center St. becomes Jewett Ave. for 0.3 miles
Turn left onto Taylor Ave. for 0.1 miles
Turn right onto OH-800 S/ Johnson Ave. for 15 miles
Left onto OH-799 for 3.2 miles
Turn left to stay on OH-799 E
Turn right onto Redeye Rd. for 0.3 miles
Turn left to continue on Redeye Rd for 2.2 miles
Turn right on Minksville Rd. for 1.9 miles
Turn right onto Bushy Fork Rd for 1.0 mile
Turn right onto Springtown Rd for 0.3 miles
Access Rd on right

It is advisable to keep the attached RUMA either in all vehicles or accessible by mobile device. All oversized/overloaded vehicles will need a permit through the ODOT website. Any route applied for with ODOT that can't be navigated will kick back with an alternate route. Please contact ASCENT RESOURCES Field Superintendent, Jeff Beck, at 614-896-0599 or jeff.beck@ascentresources.com prior to using the route. Even though ODOT approves, it still could include unauthorized roads/bridges.

*Production Traffic

PLANS PREPARED FOR:



BSA

PRODUCTION TRAFFIC
HAUL ROUTE DIRECTIONS

NOTTINGHAM TWP., HARRISON CO., OH

PLANS PREPARED BY:

