





Wagner Approved RUMA Route

From the West (I-77):

1. Take exit 44A and head east on I-70 E towards Wheeling for 6 miles.
2. Take exit 193 and turn right onto OH-513 S and continue for 2.2 miles.
3. Turn left onto Oxford Rd. and continue for 3.8 miles.
4. Turn right onto Basket Rd. and continue for 1.3 miles.
5. Turn right onto Starr Rd. and continue for 0.7 miles to the Wagner entrance.


From the South (Quaker City, OH):

1. Head north on OH-513 for 4.6 miles.
2. Turn right onto Oxford Rd. and continue for 3.8 miles.
3. Turn right onto Basket Rd. and continue for 1.3 miles.
4. Turn right onto Starr Rd. and continue for 0.7 miles to the Wagner entrance.

From the North (I-70):

1. Take exit 193 and turn onto OH-513 S and continue for 2.2 miles.
2. Turn left onto Oxford Rd. and continue for 3.8 miles.
3. Turn right onto Basket Rd. and continue for 1.3 miles.
4. Turn right onto Starr Rd. and continue for 0.7 miles to the Wagner entrance.

It is advisable to keep the attached RUMA either in all vehicles or accessible by mobile device. All oversized/overloaded vehicles will need a permit through the ODOT website. Any route applied for with ODOT that can't be navigated will kick back with an alternate route. Please contact ARU's Field Superintendent, Jeff Beck, at 614-896-0599 or jeff.beck@ascentresources.com prior to using the route. Even though ODOT approves, it still could include unauthorized roads/bridges.



E.L. ROBINSON
ENGINEERING
801 Watermark Drive, Suite 310 • Columbus, Ohio 43215
www.elrobinsonengineering.com

HAUL ROUTE MAP

DRIVING DIRECTIONS

OXFORD TWP., GUERNSEY CO., OH

[illegible]