


Angelo Staging to Pad

Jefferson County



Driving Directions

From the North:

When going southbound on OH 7, take the Picoma Road Pattons Run exit south of Yorkville.

Make a left and drive 0.2 miles to a stop sign.

Turn left and drive 0.1 mile to a stop sign.

Turn left onto Old Rt. 7 and drive 1.5 miles.

Turn left onto Public Road and make an immediate left into the staging area.

From the South:

When going north on OH 7, take the Picoma Road Pattons Run exit north of Martins Ferry.


Make a right and drive 0.1 mile to the stop sign.

Turn left and drive 0.1 mile to a stop sign.

Turn left onto Old Rt. 7 and drive 1.5 miles.

Turn left onto Public Road and make an immediate left into the staging area

From staging to Angelo Pad



When leaving the pad, make a left onto CR 2, Public Road

Drive 1.7 miles passing under OH 7.

Turn right at the top of the hill onto Jones Road.

Drive 0.3 miles. Access will be on the right.