


Angelo Pad
Temporary detour
Jefferson County




Driving Directions

From the intersection of I-470 and OH 7, drive north for 5.5 miles and turn left on CR 4, Glens Run Road.

Drive 0.5 mile and turn right on CR 16, Nixon Run Road.

Drive 4.6 miles. Turn right onto OH 647.

Drive 1.8 miles and turn right onto CR 1A as you enter Mt. Pleasant.



Driving Directions

Drive 0.1 mile to the intersection with CR 1.

Continue straight on CR 1 for 3.7 miles to the intersection with CR2 in Glen Robins.

(Note: There is a steep grade going into Glen Robbins with a sharp turn at the bottom. Gear down before starting down the grade.)

At the intersection with CR 2, go straight across the bridge and continue 0.6 mile to the top of the hill.

Turn left on to Jones Road and drive 0.4 mile. Access will be on the right.