


ANGI Take Point Haul Route

Belmont County



From the west:

From the intersection of OH 800 and OH 148 south of Barnesville, go east on 148 for 12.2 miles.

Turn left onto CR 86, Pleasant Ridge Road.

Drive 1.75 miles to the take point.

From the east:

From the intersection of OH 9 and OH 148 south of St. Clairsville, go west on OH 148 for 3.2 miles.

Turn right onto CR 86, Pleasant Ridge Road.

Drive 1.75 miles to the take point.