


Beech Spring WT Haul Route

Belmont County



Driving Directions from the north:

From the intersection of OH 647 and CR 2, Deep Run Road, south of Mt. Pleasant, drive east on CR 2 for 1.8 miles to the intersection with CR 16, Nixon Run Road.

Bear left to continue on CR 2 and make an immediate left onto Beech Spring, beginning of the project.

For access to the end of the project, instead of turning onto Beech Spring, drive another 1.8 miles on CR 2 and turn left onto TR 469, Beech Spring Road. (May be listed as Pattons Run or Nixon Run).

Drive 0.7 mile. This is the end of the project.

From the east, west and south:

From the intersection of I-470 and OH 7, drive north for 5.5 miles and turn left on CR 4, Glenns Run Road.

Drive 0.5 mile and turn right on CR 16, Nixon Run Road.

Drive 2.8 miles and turn right onto Beech Spring Road. Trucks must continue straight on use the turn around on the left 0.7 miles ahead.

For access to the end of the project, make the sharp right from CR 16 onto CR 2 and drive 1.8 miles and turn left onto TR 469, Beech Spring Road. (May be listed as Pattons Run or Nixon Run).

Drive 0.7 mile. This is the end of the project.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>

NOTE: All trucks over 100,000 must use alternate route on Barnes Road. Contact Gulfport for more information.