


# BK Stephens Haul Route

## Harrison County



### Driving Directions

#### From the west:

From the intersection of US 22 and OH 331 in Piedmont, drive 1.5 miles east on US 22.

Turn right onto TR 249, Tyson Road.

Drive .9 miles. Lease road is on the left.

#### From the east:

From the middle of Moorefield, drive .3 mile west on US 22.

Turn left onto TR 249, Tyson Road.

Drive .9 mile. Lease road is on the left.