


Brubaker AST Haul Route

Belmont County



Driving Directions

All traffic:

From the intersection of OH 7 and OH 148 in Powhattan Point, drive 2.75 miles west on OH 148.

Entrance will be on the right.