


Belmont County



Driving Directions

From the east:

From the intersection of OH 7 and US 250 in Bridgeport, drive west on US 250 for 2.8 miles.

Turn right onto TR 458, Buckeye Run.

Drive 0.4 miles. This is the end of the project.

From the west:

From the intersection of US 250 and CR 4 in Colerain, drive east on US 250 for 3.1 miles.

Turn left onto TR 458, Buckeye Run.

Drive 0.4 mile. This is the end of the project.

From the east, west and south:

From the intersection of I-470 and OH 7, drive north for 5.5 miles and turn left on CR 4, Glenns Run Road.

Drive 3 miles and turn left onto OH 647.

Make an immediate right onto TR 458, Buckeye Run. This is the beginning of the project.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>