


Carpenter Impoundment to Vaughn Impoundment



Driving Directions

When you leave the Carpenter Impoundment, turn left onto CR 128, Boston Road.


Drive 4 miles and turn right onto OH 379.

Drive 1.4 miles to a stop sign and continue straight on OH 147.

Drive 1.1 miles and turn right.

Continue for 3.4 miles into Barnesville and turn right at the stop sign onto OH 800.

Drive 19.2 miles to the signal in Woodsfield at McDonalds.



Turn right and drive 0.1 mile to the next traffic signal.

Turn left onto OH 78.

Drive 1.7 miles and turn right onto CR 41, Sugartree Cranesnest Road.

Drive 1.1 miles and turn right onto TR 354, Newhart Ridge.

Drive 0.2 miles and turn left into the Vaughn access.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>