


Cunningham Haul Route

Belmont County



Driving Directions

From the intersection of OH 800 and OH 147 in Barnesville, go west on OH 147 for 3.4 miles.

Turn left to continue on OH 147 for 1.7 miles.

(Note: Do not turn left onto OH 379 to Bolton/McCort, etc. area.)

Access is on the left.