


Dorsey Haul Route

Belmont County



Driving Directions

Note: All trucks must use this route. Turning movements are restricted from any other route.

From the east:

Take exit 218 off I-70 and turn left at the light.

Drive 0.2 mile and turn left at the light (2nd light after the turn) onto US 40.

Drive 1 mile and turn right onto CR 4, Barton Road.

Drive 1.8 miles. Access will be on the right.

From the west:

Take exit 218 from I-70 and turn right at the light.

Drive 0.5 mile and turn left at the light (3rd light after turn) onto US 40.

Drive 1 mile and turn right onto CR 4, Barton Road.

Drive 1.8 miles. Access will be on the right.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160.

Permit information can be found at <http://belmontcountyengineer.com/data/forms/>