


Farson Haul Route

Belmont County



Driving Directions

From the north:

At the intersection of OH 145 and OH 148 west of Powhatan Point, go south on OH 145 for 5.4 miles.

Turn right onto TR 1011 and TR 804, Crum Road.

Drive 1.5 miles and bear right. Access will be on the right.

From the south:

From the intersection of OH 145 and OH 556 in Beallsville, go north on OH 145 for 0.3 miles.

Turn left onto TR 1011 and TR 804, Crum Road.

Drive 1.5 miles and bear right. Access will be on the right.

This haul route is in 2 counties.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact Amy Zwick at 740-472-2537, email azwick@monroecountyengineer.com. More information can be found at <http://monroecountyohio.com/government/engineer/index.php>