


Faye Haul Route

Belmont County



Directions

From the east:

From the intersection of OH 7 and OH 148 in Powhatan Point, drive west on OH 148 for 17 miles.

Turn left onto CR 92. Drive 0.1 mile.

Turn right onto TR 521, Mt. Horeb Road. Access is on the right.

From the west:

From the intersection of OH 800 and OH 148 south of Barnesville, drive east on OH 48 for 8.7 miles.

Turn right onto CR 92 and drive 0.1 mile.

Turn right onto TR 521, Mt. Horeb Road. Access is on the right.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at

<http://belmontcountyengineer.com/data/forms/>

