


Francis Haul Route

Belmont County



Driving Directions

From OH 800 in Barnesville, turn west onto OH 147 for 3.4 miles.

Turn left onto OH 147 for 1 mile.

Turn left onto OH 379 for 5 miles.

Access is on the left.