


## **Gustina Bear Haul Route**

### **Harrison County**



### **Driving Directions**

**From the west:**

From the intersection of US 22 and OH 331 in Piedmont, drive .8 mile east on US 22.

Lease road will be on the right.

**From the east:**

From the middle of Moorefield, drive 1 mile west on US 22.

Lease road will be on the left.