


Harvey Haul Route

Monroe County



Driving Directions

From the east:

When going north or south on OH 7 in Clarington, take OH 556 west towards Beallsville. Drive 11 miles and turn left onto CR 5, Atkinson Run Road.

Drive 0.3 mile. Access will be on the left.

From the west:

From the intersection of OH 145 and OH 556 in Beallsville, drive east on OH 556 for 2 miles.

Turn right onto CR 5, Atkinson Run Road.

Drive 0.3 mile. Access will be on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact Amy Zwick at 740-472-2537, email

azwick@monroecountyengineer.com

More information can be found at

<http://monroecountyohio.com/government/engineer/index.php>