


JAC Haul Route

Belmont County



Driving Directions

From the West

From the intersection of OH 800 and OH 148 south of Barnesville, Drive 5.5 miles east on OH 148.

Turn left onto CR 26. Drive 1.2 miles. Access will be on the left.

From the East

From the intersection of OH 7 and OH 148 in Powhatan Point, drive 20 miles west on OH 148.

Turn right onto CR 26. Drive 1.2 miles. Access will be on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact the County Engineers office at 740-699-2160. Permit information can be found at

<http://belmontcountyengineer.com/data/forms/>

