


Jones Haul Route

Monroe County



Driving Directions

From the north:

From the intersection of OH 145 and OH 26 west of Beallsville, take OH 26 south for 4.5 miles.

Turn right onto CR 1, Kings Highway for 1.1 miles. Entrance will be on the right.

Any loads requiring an ODOT moving permit will also require a county moving permit.

Contact Amy Zwick at 740-472-2537, email azwick@monroecountyengineer.com

More information can be found at <http://monroecountyohio.com/government/engineer/index.php>