


Kage Haul Route

Harrison County



Driving Directions

Note: this pad is only accessible from the south.

From the 4-way stop on OH 800 in Freeport (north of US 22), go north on OH 800 for 8.2 miles.

Turn right onto TR 290, Ferguson Road.

Drive 1.2 miles and turn right onto TR 291, Laughlin Road.

Drive 0.7 mile. Access will be on the left.

All oversize loads that require pilot cars will be required to escort the load to the pad.