


Keyser AST Haul Route

Belmont County



From the west:

From I-70

Going eastbound on 70, take Exit 220 and turn right onto CR 214, Bellaire High Ridge Road.

Drive 1.9 miles and turn right onto CR 30, Dixon Run Road.

Drive 1.2 miles and turn left onto TR 624, McCurdy Road.

Drive 500'. Access is on the left.

From I-470

Going eastbound on I-470, take exit 3 and turn left onto CR 214, Bellaire High Ridge Road.

Drive 1.1 miles and turn left onto CR 30, Dixon Run Road.

Drive 1.2 miles and turn left onto TR 624, McCurdy Road.

Drive 500'. Access is on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>

From the East:

From I-70

Going westbound on I-70, take Exit 220 and turn left onto US 40.

Drive 0.1 mile and turn left onto CR 214, Bellaire High Ridge Road.

Drive 2.0 miles and turn right onto CR 30, Dixon Run Road.

Drive 1.2 miles and turn left onto TR 624, McCurdy Road.

Drive 500'. Access is on the left.

From I-470

Going westbound on I-470, take exit 3 and turn right onto CR 214, Bellaire High Ridge Road.

Drive 1 mile and turn left onto CR 30, Dixon Run Road.

Drive 1.2 miles and turn left onto TR 624, McCurdy Road.

Drive 500'. Access is on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>