


Kinyo 2.0 Pad Haul Route

Jefferson County



From the south:

Driving Directions


While going north on OH 7, take the Rayland-Dillonvale exit for OH 150 north of Tiltonsville.

Make a right onto Liberty Avenue at the bottom of the exit and drive 0.25 miles.

Turn right onto OH 150.

Drive 0.5 miles through town and turn right onto CR 15, Warren Ridge-Smithfield-Rayland Road.

Drive 0.25 miles and turn left up the hill to stay on CR 15.



Drive 3.4 miles on CR 15.

Turn left onto CR 14, Connerville Road.

Drive 0.5 mile.

Access will be on the right.

Please note that in order to leave on OH 7 south, make a left onto Old State Rt. 7 just past the railroad tracks and prior to the overpass in Rayland and drive 0.5 miles to the on ramp.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact Eric Hilty at 740-283-8574

From the north:

Driving Directions

While going south on OH 7, take the Rayland Dillonvale exit for OH 150 south of Brilliant.

Make a left at the bottom of the ramp and drive 0.3 miles.

Turn right onto OH 150.

Drive 0.5 miles through town and turn right onto CR 15, Warren Ridge-Smithfield-Rayland Road.

Drive 0.25 miles and turn left up the hill to stay on CR 15.

Drive 3.6 miles on CR 15

Access will be on the right.

Please note that in order to leave on OH 7 north, continue straight past the railroad tracks and past the overpass.

Make a left onto Liberty Avenue.

Drive 0.3 mile to the north bound on ramp.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact Eric Hilty at 740-283-8574