


Koy Fields AST Farm

Monroe County



Driving Directions

From the intersection of OH 800 and OH 26 south of Woodsfield, drive south on OH 26 for 9 miles.

Turn right onto OH 537.

Drive 2.2 miles. Entrance will be on the left.