




Krupa Temporary Truck Haul Route

Belmont County





Driving Directions

From the east and north and all I-70/I-470 traffic:

From the I-470 and OH 7 intersection west of Wheeling, drive 8.8 miles south on OH 7.

Turn right onto TR 534, Broadview Road.

Drive 1.8 miles and turn left onto TR 296, Cash Ridge Road.

Drive 2.5 miles. Access will be on the left.

From the south:

From the intersection with the Moundsville Bridge in Dilles Bottom, drive south on OH 7 for 2.4 miles.

Turn right onto CR 54, Pipe Creek Road.

Drive 1.4 miles and turn right onto TR 293, Kirkland Hill Road.

Drive 2.5 miles and turn left onto TR 298, Lockwood Run Road.

Drive 0.5 mile and turn right onto TR 296, Cash Ridge.

Drive 2 miles. Access will be on the right.

From the west below I-70:

From the OH 9 and OH 147 intersection in Centerville, OH (OH 9 south of St. Clairsville), drive east on OH 147 for 6.2 miles.

Turn right onto CR 48, Wegee Road just past the gasoline station/corner store.

Drive for 0.9 mile and turn right onto TR 296, Cash Ridge Road.

Drive 1.4 mile and keep left on Cash Ridge Road at the intersection.

Drive 1.6 miles. Access will be on the right.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact John Parkinson at 740-699-2160. Permit information can be found at <http://belmontcountyengineer.com/data/forms/>

Any load requiring an ODOT moving permit will also need a Mead Township permit. Contact Ed Good at 740-312-8411