


# Lorna Haul Route Belmont County



## Driving Directions

### From the west

From the Ohio SR 800/148 intersection south of Barnesville, take 148 east for 10.9 miles. Access is on the left.

### From the north (not recommended for large trucks)

Take Ohio SR 9 south from Exit 215 on I-70 for 14.5 miles.

Turn right onto Ohio SR 148.

Go 4.7 miles. Access will be on the right.

### From the east and south

At the Ohio SR 7/148 intersection in Powhatan Point, take SR 148 for 15.6 miles.

Access will be on the right.