


Lyon Haul Route

Harrison County



Driving Directions

From the intersection of OH 800 and OH 799 northeast of Freeport, drive 1.1 miles north on OH 800.

Turn left onto CR 61, Friendly Ridge for 3.2 miles.

Entrance will be on your right.

Any loads requiring an ODOT moving permit will also require a county moving permit.

Contact Kris Miller at 740-942-8867. More information can be found at

<http://www.harrisoncountyohio.org/county-engineer-permits>