


Marchbank Haul Route

Jefferson County



Driving Directions

From the intersection of US 250 and OH 150 (This needs to be approached from the west) west of Mt. Pleasant, drive east on OH 150 for 3.7 mile into Mt. Pleasant.

In Mt. Pleasant, OH 150 will turn left. Go straight through the intersection onto OH 647 for 0.5 mile.

Bear left onto CR 1A, Mt. Pleasant-Glen Robbins Road.

Drive 3 miles and turn left onto TR 113, Mt. Pleasant Road.

Drive .3 miles. Access will be on the left.

Any loads requiring an ODOT moving permit will also require a county moving permit. Contact Eric Hilty at 740-283-8574