


McCort Haul Route

Belmont County



Driving Directions

From OH 800 in Barnesville, turn west onto OH 147 for 3.4 miles.

Turn left onto OH 147 for 1.1 miles.

Turn left onto OH 379 for 1.4 miles.

Turn left onto CR 128, Boston Road/Main Street for .8 mile.

Access is on the right.

Any loads requiring an ODOT moving permit will also require a county moving permit.
Contact John Parkinson at 740-699-2160. Permit information can be found at
<http://belmontcountyengineer.com/data/forms/>