


MEC Haul Route

Belmont County



Driving Directions

From the west:

From the intersection of OH 800 and OH 148 south of Barnesville, go east on 148 for 6.8 miles.

Access will be on the left.

From the east:

From the intersection of OH 9 and OH 148 south of St. Clairsville, go west on OH 148 for 8.6 miles.

Access will be on the right.